

# Imray Correction Notice

ICC48-1

20 September 2012

## Chart C48 WGS 84

*Edition Feb 2010*

*Date of printing Feb 2010*

The following corrections should be noted:

### 1 Muros (Plan G)

Amend Lt Fl.R.5s3M to Fl(4)G.11s3M in 42°46'·67N 9°03'·30W (ILNW 104/10)

### 2 Entrance to Rio Douro

Substitute Siren(2)30s for Lt Fl.R.5s9M Siren(1)30s in 41°08'·81N 8°40'·64W.

Insert Lt 2Ldg Oc.Y.5s6M in 41°08'·85N 8°40'·30W (ILNW 161/10)

### 3 C. Silleiro westwards

Delete Y pillar Lt buoy Q(5)Y.15s in 42°07'·70N 9°23'·72W (ILNW 178/10)

### 4 Vilagarcia de Arousa (Plan H)

Insert Lts:

Dir.Fl.WRG.6s15-12M in 42°36'·41N 8°46'·07W

Fl(2)G.7s in 42°36'·02N 8°47'·12W

Fl(2)G.7s in 42°36'·01N 8°46'·84W

Delete G pillar Lt buoy Fl.G.5s close N of Fl(2)G.7s Lts. (ILNW 210/10)

### 5 Ria de Pontevedra, Raxo (Plan J)

Amend Lt Fl(2)R.8s3M to Fl(4)R.11s5M in 42°24'·10N 8°45'·26W (ILNW 211/10)

### 6 Cabo Ortega

Amend Pta de los Aguillones Lt to Fl(2+1)15s122m18M in 43°46'·2N 7°52'·3W (ILNW 212/10)

### 7 Ria de Pontevedra, Sanxenxo (Plan J)

Amend Lt Q.R to Fl.R in 42°23'·81N 8°48'·06W (ILNW 235/10)

### 8 Boca del Sudoeste westwards (Plan J) (*buoy removed - see ILNW 394/12*)

Insert Y ODAS Fl(5)Y.20s3M Lt buoy in 42°18'·93N 8°57'·61W (ILNW 258/10)

### 9 Approaches to Vigo (Main chart & Plan K)

Insert Y ODAS Lt buoy Fl(5)Y.20s in 42°05'·82N 8°56'·30W (ILNW 326/10)

### 10 Cabo Silleiro westwards

Move ODAS Q(5)Y.20s Lt buoy in 42°07'·17N 9°24'·11W to 42°07'·16N 9°25'·78W (ILNW 451/10)

### 11 Pta de la Estaea de Bares northwards (*Correction amended - see ILNW 183/11*)

Move ODAS Lt buoy Fl(5)Y.20s in 44°03'·7N 7°37'·0W to 44°04'·5N 7°41'·1W (ILNW 466/10)

### 12 Ria de Arousa, Punta del Chazo northeastwards (Plan H)

Delete R pillar Lt buoy Fl(3)R.10s in 42°36'·77N 8°50'·14W (ILNW 482/10)

### 13 I. Sisargas northwestwards (*Correction amended - see ILNW 93/12*)

Move ODAS Q(5)Y.20s Lt buoy in 43°29'·71N 9°12'·64W to 43°29'·62N 9°15'·59W (ILNW 483/10)

### 14 Ria de Arousa, A Pobra do Caramiñal (Plan H)

Delete Lt buoy Fl(2)R.8s in 42°36'·15N 8°55'·72W (ILNW 499/10)

### 15 Rias de Ares and Betanzos (Plan C)

Insert Y pillar Lt buoy Fl(4)Y.11s with x topmk in:

43°25'·60N 8°16'·79W

43°25'·40N 8°16'·36W (ILNW 510/10)

### 16 Ria de Arosa, Vilanova de Arosa (Plan H)

Delete RW Lt bn Fl.R.5s3M in 42°34'·11N 8°50'·45W (ILNW 546/10)

**17 Ribadeo, Isla Pancha**

Delete fog signal Siren Mo(R)30s at Lt in 43°33'·39N 7°02'·52W (ILNW 99/11)

**18 Apps to La Coruña, Punta Mera (Main chart & Plan D)**

Amend Lt Fl.4s8M to LFl.8s8M in 43°22'·96N 8°21'·08W (ILNW 100/11)

**19 La Coruña (Plan D)**

Amend duration at Lts Fl(2+1)R.21s to 15s in:

43°21'·44N 8°22'·71W

43°22'·02N 8°23'·72W (ILNW 101/11)

**20 Cabo Villano (Main chart & Plan F)**

Delete fog signal SirenMo(V)60s at Lt in 43°09'·63N 9°12'·69W (ILNW 113/11)

**21 Punta de la Estaca de Bares northwards**

Move ODAS Lt buoy Q(5)Y.20s in 44°04'·5N 7°41'·1W to 44°07'·4N 7°40'·3W (ILNW 183/11)

**22 Ria de Ares, Pta Lousada southwestwards (Plan C)**

Insert dangerous rock symbol in 43°24'·46N 8°12'·48W (ILNW 230/11)

**23 Ría de Camariñas (Main chart & Plan F)**

Amend range of Pta de la Barca Lt from 6M to 10M in 43°06'·78N 9°13'·18W (ILNW 231/11)

**24 Approaches to La Coruña, Torre de Hércules (Plan D)**

Delete fog signal SirenMo(L)30s7M in 43°23'·24N 8°24'·41W (ILNW 258/11)

**25 La Coruña**

Delete fog signal SirenMo(L)30s at Torre de Hércules Lt in 43°23'·24N 8°24'·41W (ILNW 259/11)

**26 Punta Estaca de Bares**

Delete fog signal Siren Mo(B)60s at Lt in 43°47'·18N 7°41'·05W (ILNW 31/12)

**27 Leixões (Plan N)**

Harbour works at Leixões are now complete.

Full details will be included on the next edition of this chart. (ILNW 67/12)

**28 Islas Sisargas northwestwards**

Move Y ODAS Lt Q(5)Y.20s from 43°29'·62N 9°15'·59W to 43°30'·03N 9°12'·60W (ILNW 93/12)

**29 Ria de Pontevedra, Porto Novo (Plan J)**

Amend Lt Fl(3)R.6s to Fl(2)R.7s in 42°23'·65N 8°49'·14W (ILNW 304/12)

**30 La Coruña, Torre de Hércules (Main chart & Plan D)**

Insert AIS at Lt Fl(4)20s104m23M in 43°23'·16N 8°24'·39W (ILNW 305/12)

**31 Automatic Identification Systems**

Insert AIS at Lts:

Punta de la Estaca de Bares Fl(2)7·5s99m25M in 43°47'·17N 7°41'·06W

Cabo Ortegá Fl(2+1)15s18M in 43°46'·27N 7°52'·18W

Punta Candelaria Fl(3+1)24s87m21M in 43°42'·67N 8°02'·95W

C. Corrubedo Fl(2+3)WR.20s31m15M Siren Mo(O)60s Racon(K) in 42°34'·57N 9°05'·39W (ILNW 305/12)

**32 Cabo Villano (Main chart & Plan F)**

Insert AIS at Lt Fl(2)15s102m28M Racon(M) in 43°09'·63N 9°12'·69W (ILNW 305/12)

**33 Ria de Arosa (Main chart & Plan H)**

Insert AIS at Lts:

Isla Salvora Fl(3+1)20s39m21M & Fl(3)20s in 42°27'·97N 9°00'·81W

I. Rua Fl(2)WR.7s12M Racon(G) in 42°32'·96N 8°56'·38W (ILNW 305/12)

**34 Ria de Pontevedra, Isla Ona (Main chart & Plan J)**

Insert AIS at Lt Fl(4)24s126m25M in 42°22'·95N 8°56'·19W (ILNW 305/12)

**35 Ría de Vigo, Islas Cíes (Main chart & Plan K)**

Insert AIS at I. del Faro Lt Fl(2)8s186m22M in 42°12'·85N 8°54'·90W (ILNW 305/12)

**36 Ría de Pontevedra (Plan J)**

Delete Y ODAS Lt buoy Fl(5)Y.20s3M in 42°18'·93N 8°57'·61W (ILNW 394/12)

**37 Ría de Pontevedra (Plan J)**

Replace G pillar Lt buoy Fl(4)G.11s3M with N card pillar Lt buoy VQ in 42°22'·66N 8°44'·20W (ILNW 416/12)